




MALE STRAIGHT CLAMP CONNECTOR FOR 1/2" RIGID COAXIAL CABLE	
CODE AP3641	N SERIES 50 OHMS
IEC STANDARD 169-16	WEIGHT: 113,75g






ASSEMBLY INSTRUCTIONS:

Cable cutting



38,3


Cut the cable as shown and insert the O-ring.



31, 7,3, 38,3

Fit the reducer until it touches the O-ring and fold the part shown in the drawing until it touches the reducer.

Solder the pin to the center conductor, keeping the outer surface clean



reductor
soldar

Dobrar cabo até encostar no reductor

Insert the cable into the body and tighten with a wrench

